

State Water Resources Control Board

May 30, 2017

(Via email and Certified Mail)

CERTIFIED MAIL
NO. 7015 1520 0001 8017 2266

Mr. Barry Halloway
Director of Engineering
City of Healdsburg
401 Grove Street
Healdsburg, California 95448
healdsburgaviation@vbbn.com

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEM
LOCATED AT THE HEALDSBURG AIRPORT, 1500 LYTTON SPRINGS ROAD,
HEALDSBURG**

Dear Mr. Halloway:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the UST at your facility on May 24, 2017, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Install Line Leak Detectors (LLD) According to Manufacturer's Instructions – The Vaporless Manufacturing Inc., LLD. vent tubes are required to be stainless steel for jet fuel and aviation gas.	West	May 24, 2017	Ongoing	23 CCR 2638(a)
2	Failure to Monitor Product Piping – The sensor in the west turbine sump was unable to detect a leak at the earliest opportunity because the test boot was positioned upward. The test boot needs to be pulled back from the secondary containment or positioned so that the testing port/valve is pointed downward between the three and nine o'clock position.	West	May 24, 2017	Ongoing	23 CCR 2630(d)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Healdsburg Fire Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Mr. Joseph Lovesee
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
joseph.lovesee@waterboards.ca.gov

Local CUPA

Ms. Linda Collister
Fire Marshal/Division Chief
City of Healdsburg Fire Department
601 Healdsburg Avenue
Healdsburg, California 95448
lcollister@ci.healdsburg.ca.us

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: *(via email only)*

Ms. Linda Collister
Fire Marshal/Division Chief
City of Healdsburg
lcollister@ci.healdsburg.ca.us